

**ERRATA**

**Title:** PCI Devices Interrupt Routings Corrections – 5/22/02  
**Document Title:** NetCARDII User Manual  
**Document No:** C2i-PRNETII-UM-010

1. Page 17: The table 7 should be revised as follows:

Previous:

| PCI Device | IDSEL | Device # | INTA# | Connection to INTx# signal |       |       |
|------------|-------|----------|-------|----------------------------|-------|-------|
|            |       |          |       | INTB#                      | INTC# | INTD# |
| R5C476II   | AD19  | 08H      | INTA# | INTA#                      |       |       |
| 82559#1    | AD27  | 10H      | INTA# |                            |       |       |
| 82559#2    | AD28  | 11H      |       | INTA#                      |       |       |
| CS4281     | AD29  | 12H      |       |                            | INTA# |       |

Revised:

| PCI Device | IDSEL | Device # | INTA# | Connection to INTx# signal |       |       |
|------------|-------|----------|-------|----------------------------|-------|-------|
|            |       |          |       | INTB#                      | INTC# | INTD# |
| R5C476II   | AD19  | 08H      | INTA# | INTB#                      |       |       |
| 82559#1    | AD27  | 10H      | INTA# |                            |       |       |
| 82559#2    | AD28  | 11H      |       | INTA#                      |       |       |
| CS4281     | AD29  | 12H      |       |                            | INTA# |       |

Shading indicates the difference between previous edition and revised edition.